


03500.014383

*Cofc*  
PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

HIROYUKI TAKAHASHI

Appl. No.: 09/498,627

Filed: February 7, 2000

For: INFORMATION PROCESSING  
APPARATUS FOR DISPLAYING  
DATA RELATED TO IMAGE  
FORMING APPARATUS, AND  
INFORMATION PROCESSING  
METHOD THEREFOR

U.S. Patent No.: 6,864,991 B1

Issued: March 8, 2005

) Examiner: S. Ebrahimi

) Art Unit: 2626

) March 8, 2006

*Certificate*  
APR 03 2006  
of Correction

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

The following minor errors have been noted in the above-identified patent:

SHEET 36

Figure 36, "ROUTER" (all occurrences) should read --ROUTER--.

COLUMN 1

Line 17, "4" should be deleted.

### COLUMN 3

Line 54, "router 3205" should read --router 3605--; and  
Line 56, "line 3208" should read --line 3608--.

### COLUMN 4

Line 55, "B-bit" should read --8-bit--; and  
Line 59, "Since" should read --since--.

### COLUMN 5

Line 12, "K1/and" should read --K1 and--.

### COLUMN 6

Line 11, "bitmapped" should read --bit-mapped--.

### COLUMN 7

Line 44, "black (B)" should read --black (K)--.

### COLUMN 9

Line 51, "above described" should read --above-described--.

### COLUMN 10

Line 8, "configuration tab 1207" should read --configuration tab 1206--;  
Line 45, "were are" should read --have been--;  
Line 58, "above described" should read --above-described--; and  
Line 64, "17 cm" should read --17 in--.

### COLUMN 11

Line 23, "Buttons 1310 to 1309" should read --Buttons 1303 to 1309--;  
Line 48, "Qn," should read --on,--; and  
Line 63, "cursor 150" should read --cursor 1510--.

### COLUMN 12

Line 16, "1903. Thus" should read --1903, thus--;  
Line 55, "london" should read --London--; and  
Line 59, "client distance." should read --client.--.

COLUMN 14

Line 28, "step 3402" should read --step S3402--; and  
Line 36, "elapses," should be deleted.

COLUMN 15

Line 23, "above described" should read --above-described--; and  
Line 57, "above described" should read --above-described--.

COLUMN 16

Line 8, "above described" should read --above-described--.

These errors appear to be relatively insignificant and, therefore, we do not believe it is necessary to request a Certificate of Correction. However, it is requested that this paper be placed in the filewrapper of the above-identified patent.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

  
Leonard P. Diana  
Attorney for Patentee  
Registration No.: 29,296

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200